



<p><b>4. Location: Retail 4<sup>th</sup> floor – POSB HQ</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model: <b>M5360rx</b></p> <p>Serial Number: 0DGsbJfK10000ZB</p> <p>Error Message: Replace new Imaging unit</p>		1	
<p><b>5. Location: Masvingo</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model: <b>M5360rx</b></p> <p>Serial Number: 0DGsbJfK100012L</p> <p>Error Message: Replace new transfer roller life. Replace new fuser Unit.</p> <p>Replace New Imaging Unit</p> <p>Replace tray 1 transfer roller.</p>		1	
<p><b>6. Location: Marondera</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model: <b>Multiexpress M5360rx</b></p> <p>Serial Number: 0DGsbJfK10000TZ</p> <p>Error Message: Replace New Imaging Unit</p>		1	
<p><b>7. Location: Nelson Mandela - Harare</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model: <b>Multiexpress M5360rx</b></p> <p>Serial Number: 0DGsbJfK200008F</p> <p>Error Message: Replace new Imaging unit. Replace new Transfer roller life.</p>		1	

<p><b>8. Location: Kwekwe</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model: <b>Multiexpress M4080fx</b></p> <p>Serial Number: 0881BJEJ30002GZ</p> <p>Error Message: Replace new transfer roller life. Replace new fuser Life. Replace tray 1 transfer roller.</p>		1	
<p><b>9. Location: Chitungwiza</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model: <b>Multiexpress M4080fx</b></p> <p>Serial Number: 0DGSBJFK20000QK</p> <p>Error Message / Problem: Replace new fuser unit.</p>		1	
<p><b>10. Location: Highglen - Harare</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model: <b>M5370RX</b></p> <p>Serial Number: <b>07QABJFH70000SL</b></p> <p>Error Message: Replace new fuser Unit. Replace New Imaging Unit</p>		1	
<p><b>11. Location: Finance - POSB HQ</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model: M5360rx</p> <p>Serial Number: 0DGSBJFK100013E</p> <p>Error Message: Replace new transfer Fuser life. Replace new fuser Unit. Replace tray 1 transfer roller.</p>		1	

<p><b>12. Location: External Salaries - POSB HQ</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model:M5360rx</p> <p>Serial Number: 0DGSBJFK20000GW</p> <p>Error Message: Replace new fuser unit.</p>		1	
<p><b>13. Location: Fort Street - Bulawayo</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model:M5360rx</p> <p>Serial Number: <b>07QABJFH700016J</b></p> <p>Error Message: Replace with new imaging unit. Replace transfer roller. Replace sensor CTD.</p>		1	
<p><b>14. Location: Gweru</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model:M5360rx</p> <p>Serial Number: <b>0DGSBJFK10001BZ</b></p> <p>Error Message: Replace with new imaging unit. Replace transfer roller. Replace fuser unit. Replace pick up roller.</p>		1	
<p><b>15. Location: Bulawayo Main</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model:M5360rx</p> <p>Serial Number: <b>0DGSBJFK10000MR</b></p> <p>Error Message: Replace with new imaging unit. Replace transfer roller. Replace sensor CTD. Replace pick up roller.</p>		1	

<p><b>16. Location: Haylet 1 - Bulawayo</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model:M5360rx</p> <p>Serial Number: <b>0881BJEJ30002HV</b></p> <p>Error Message: Service</p>		1	
<p><b>17. Location: Haylet 2 - Bulawayo</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model:M4080fx</p> <p>Serial Number: <b>0881BJEJ30002FX</b></p> <p>Error Message: Replace new transfer Fuser Unit. Replace new Tray. Replace tray 1 transfer roller. Replace main pick-up transfer roller.</p>		1	
<p><b>18. Location: Ascot - Bulawayo</b></p> <p>Make: <b>SAMSUNG</b></p> <p>Model:M5360rx</p> <p>Serial Number: <b>ODGSBJFK10000NM</b></p> <p>Error Message: Replace transfer roller</p>		1	

**YOUR OFFER MUST CLEARLY STATE THE FOLLOWING:**

- The applicable currency – Bidders must submit their bids in USD and payment will be processed in USD nostro.
- Payment terms should be clearly stated and to be after delivery. POSB shall not consider demands for cash upfront unless an advance payment guarantee has been provided by the supplier.

- Validity period of quotation to be a minimum of 30 days.
- Bidders must state completion time/ delivery period from receipt of official order.
- Bidders must attach material data sheet where applicable.
- Bidders must note that if they put more than one option only their main offer will be evaluated.
- Value added tax must be clearly and separately quoted.

**Bidders must also submit the following documents.**

1. Bidders must attach CR14 certificate – list of directors.
  2. Bidders must attach proof of registration with Procurement Regulatory Authority of Zimbabwe (PRAZ) in the form of a valid PRAZ certificate.
  3. Bidders must attach Value Added Tax Certificate
  4. Bidders must attach their valid ITF263 Tax clearance certificate.
- **Failure to comply with the terms and conditions set out in this RFQ will lead to automatic disqualification.**

**SUBMISSION OF OFFERS/ QUOTATIONS**

- Due to the COVID-19 restrictions, the bank will only be accepting electronic submissions forwarded by email. Bids must be endorsed with the above tender number on the email subject and be sent only to the email address [rfqs@posb.co.zw](mailto:rfqs@posb.co.zw).
- **NB Offers not received by 10:00 hours on the closing date SHALL be treated as late tenders and will not be considered.**

<b>Posted date</b>	11/07/2023
<b>Closing date</b>	<b>12/07/2023</b>
<b>Cosing time</b>	<b>1000 hours</b>

