

| Location | Scope |
|---------------|---|
| | |
| Esteem Harare | Attend to faulty panic button not working |
| | - Service mantrap booth |
| | Replace exit robot light |
| Causeway | - Service & reprogramming of stand-alone biometric access |
| | control |
| | - Provision for |
| | 1 x Mimic panel for double booth |
| | • 4 x Infra-red wooden beam |
| | 4 x Cherry mantrap robot green |
| | 4 x Cherry Mantrap robot red |
| | 1 x ZK Teco MA300BT biometric Fingerprint |
| | 2 x 7Amp Battery centurion |
| Kadoma | - Attend to Mantrap booth shopfitting |
| | - Provision for: |
| | 1 x Door closer – light duty Dorma door closer |
| | • 2 x 7amp Battery centurion |
| | 1 x Securi - Prod slim line push button |
| Mutare | - Attend to Mantrap booth shopfitting |
| | - Provision for: |
| | 2 x Door Closer – Light duty Dorma door closer |
| | 2 x Cherry mantrap robot green |
| | 2 x Cherry mantrap robot red |
| | 16 X hinges |
| | • 2 x 7amp Battery centurion |
| | • 100m x 4 core 2 pair solid communication cable |
| | • 20 x 3Core Cabtyre |
| | - Replacement of Kick rail systems with new emergency panic |
| | button, and make provision for, |
| | • 9 x Emergency panic buttons |
| | 1 x Sheltronic RX 2CH |
| | • 3 x Sheltronic TX 2CH |
| Bindura | - Servicing of alarm systems |



| | - Attend to delayed transmission to reaction group |
|-------------|--|
| Westgate | Service & repair of Mantrap booth Constantly trapping clients. |
| Kopje plaza | Service alarm Constantly sending false alarm Replace faulty supervisor panic button |
| Southerton | Attend to Mantrap and intruder service and remount alarm Replace 4 x Door closer -light duty Dorma door closer 2 x Cherry Mantrap robot green 2 x 7amp Battery centurion Provision for shopfitting |
| Chinhoyi | Attend to Mantrap both Make provision for: 1 x Bankbooth 521 Controller mantrap board- Cherrytech 2 x 7amp Battery centurion 1 x Door hinges 1 x Cherry mantrap robot red 1 x Cherry mantrap robot green |